

Lighting Initiatives

FACTS:

- 3493 exterior lights on the Keele campus
- 307 exterior lights on the Glendon campus
- Commitment to keep light outages below 100 (3 year avg. at 3% of lights out)
 - Current outages are higher due to construction related damage
- New LED standard; brighter light, better visibility
- \$100,000 commitment to lighting upgrades for 2013-2014

How we monitor:

1. Two Maintenance Electricians start at 6:00am. They tour the campus identifying dark areas to prioritize.
2. Weekly audit of the campus is completed by goSAFE on Sunday nights (Figures 1 & 2).
3. "Lights out" on the web is checked daily. Work orders are issued and compared for duplication with the weekly audit.
4. Calls to maintenance 22401 or emails to lightout@yorku.ca for lights out. Work orders are issued and compared for duplication with the weekly audit.

Figure 1 – Lighting and ADO Audit, Keele

KEELE CAMPUS		EXTERNAL LIGHTING		ADO CHECKS	
Total Emergency:	0 of 51 out	Total City Lights:	6 of 75 out	Total Exterior ADOs:	10 of 149 out
Total Pot Lights:	76 of 1207 out	Total Seneca Lights:	23 of 82 out	Total Interior ADOs:	14 of 206 out
Total Wallpacks:	44 of 899 out				
Total Street Lights:	36 of 1189 out				
Grand Total Out:	156 of 3493 out				





Figure 2 – Lighting and ADO Audit, Glendon

KEELE CAMPUS		EXTERNAL LIGHTING		ADO CHECKS	
Total Emergency:	1 of 10 out	Total City Lights:	0 of 0 out	Total Exterior ADOs:	1 of 26 out
Total Pot Lights:	4 of 47 out			Total Interior ADOs:	2 of 16 out
Total Wallpacks:	2 of 98 out				
Total Street Lights:	2 of 137 out				
Grand Total Out:	9 of 307 out				



SAFER TOGETHER



Download the York U Safety app and report light outages directly from your phone!

An initiative of the Community Safety Council
yorku.ca/safety

